

#### LC-DC04 Universal I/O Interface

Four Channels I/O Push Buttons Interface



### **Operating Instructions**

for authorised electricians



Important Safety Notes
Installation and commissioning of the device can only be carried out by authorised electricians. The relevant standards, directives, regulations and instructions must be observed. The devices are approved for use in the EU and have the CE mark.




## **Operating Parts**

- (1) KNX bus terminal
- (2) Programming key
- (3) Red programming Led
- (4) I/O cables

## Installation

- (1) Connect the Universal I/O Interface to the KNX cable
- (2) Wire up the Universal I/O Interface as described in the circuit diagram
- (3) Insert Universal I/O Interface in a wiring box or behind a push button
- (4) Switch on KNX power supply and provide ETS program



# Data

Number of Inputs Internal Contact Voltage Permitted Wire Gauge **Power Supply** Power Consumption Permitted Input Cable Length Operation Temperature Range Enclosure Design

3,3V KNX terminal (0,8mm<sup>2)</sup> KNX bus (29V) <0,25W 10m [0-45]°C ÎP 20 54mm x 44mm x 17mm

